Carnaby HE2 Firmware 0.4.2 Release Notes

Carnaby HE2 firmware 0.4.2 will not work with earlier versions of Carnaby HE2 Control. You will need to update the Carnaby HE2 Control to version 0.4.6.

Improvements

- Mode switching parameter change reliability improvements
- LED brightness defaults to 50%
- Mid band with high gain settings